Docket No. 217 - Development and Management Plan Inspection

Northeast Utilities Service Company Certificate of Environmental Compatibility and Public Need for the construction of a 345-kV electric transmission line and reconstruction of an existing 115-kV electric transmission line between Connecticut Light and Power Company's Plumtree Substation in Bethel, through the towns of Redding, Weston, and Wilton, and to the Norwalk Substation in Norwalk, Connecticut.

Date: November 10, 2005

Inspector: Don Ukers

Location: Overhead Line (Composite 345kV and 115kV Gallows Hill to Archers Lane)

Storm/

Rain Event: Approximately 0.5- 0.65" of rain fell over 11/9-11/10 as reported by NOAA

Areas of Inspection	Observation	Recommended Action	
Access Roads and Adjacent Roadways	- The ROW is accessible from Gallows Hill Road by an existing trail path with a swing gate, an approved access path in from the east of the ROW, and the access road previously used for the Archers Lane substation. 11/10/05 - The ROW is less muddy but remain aware of any ruts created from tracking. 11/10/05	-Most roads are in good shape. Consider using mats whenever the soil is not stable enough. If any areas still have ruts at the end of the work, it will have to be regraded to return to original conditions. 11/10/05	
	-All low spot/wetland crossings along the ROW have worked very well to filter out sediment from the wetland. 11/10/05 - Sediment tracking was not noted at Gallows Hill during this inspection. 11/10/05	- The wetland areas will be restored when all work in this section is completed as this is considered temporary access. See erosion control section for more detail. 11/10/05 - Continue to monitor for any issues. 11/10/05	
Foundation construction	-Open excavations and drilling operations continue at a number of structure locations along the ROW on both the Gallows Hill and Archers Lane portions. 11/10/05	- Although there were some stockpiles placed at some sites, most are in upland areas and well contained. 11/10/05	
	-Several poles were in place adjacent to the foundation in preparation for installation. A pole structure was also being	-None at this time. 11/10/05	

Areas of Inspection	Observation	Recommended Action
	offloaded to the ROW during the inspection. 11/10/05 -Drilling operations were underway in preparation for a structure foundation adjacent to Archers Lane. 11/10/05	- None at this time. 11/10/05
	- Concrete foundations also continue to be constructed in several locations. 11/10/05	- None at this time. 11/10/05
	- Installation of grounding wire was also noted at one location. 11/10/05	- None at this time. 11/10/05
Erosion and Sediment	-Silt fence is still mostly in	- The silt fence has done a
Controls (includes inspection within 24	place along the low wetland spots on the access path.	very good job of keeping turbid water out of the
hours of a storm event)	Continue to check status of silt	wetlands. It should be
Erosion and Sediment Controls	fence along the crossings. 11/10/05	maintained as needed to continue its use. 11/10/05
	- The spot near Archers Lane is working well and clear standing water was noted in the adjacent wetlands. 11/10/05	- None at this time. 11/10/05
	- Further sedimentation was not noted in the wetland near Gallows Hill and haybales were still in place. 11/2- 11/10/05	-Continue to monitor this area but none at this time. 11/2-11/10/05
	- Silt fence was in place around several stockpiles on the ROW. Almost all are in upland locations. 11/10/05	- Silt fence could be extended along at one of the upland piles if sedimentation issues are noted. 11/10/05
	- Two separate tarp/basins were noted on the ROW which were used either for concrete washouts or dewatering the foundations. 11/2-11/10/05	- Continue to use these areas as needed and maintain them. 11/10/05
	- Conditions had dried out at the transition station/ROW edge where clearing had occurred for the new structure. 11/10/05	-Extend erosion control in this location if it becomes necessary. 11/10/05
	-The D&M plan approved	- None at this time, the
Inland Wetland and	stone on geotextile fabric at	crossings have been used

Areas of Inspection	Observation	Recommended Action
Watercourse encroachment and mitigation	the first wetland crossing is still working very well but continue to toe in fence as necessary. 11/2/05 -The wetlands at the Archers Lane low spot/crossing are well protected and clear standing water was noted here.11/10/05	consistently. As the access is considered temporary, the stone will be removed when final work ends so the wetlands can be restored. 11/10/05 - None at this time. 11/10/05
State species of concern, threatened and endangered species	- The overhead portions have been identified as having potential habitat for several state listed species, including several species of turtles and plants. This particular portion of overhead work includes the turtle habitat area. 9/15-11/10/05 -The Eastern box turtle has not been observed since the first sighting and are likely in the process of hibernating.	-Crews have been doing daily sweeps for any turtles in the work areas and noting the results of their efforts on daily construction reports. 11/10/05
Vegetative clearing limits (including trees to save or danger trees noted)	11/10/05. -The ROW had been mowed in this section in order to allow for truck access and foundation construction. Vegetation that did not need to be removed was left in place on either side of the access path 9/15-11/10/05 - Clearing at the Archers Lane/ROW edge was done by CL&P for the recently approved access road to a new structure to be constructed just off the station yard. 11/2-11/10/05	-None at this time. In general limit clearing to those areas necessary. 11/10/05 - Extend erosion controls here if necessary. 11/10/05
Dewatering	- Active dewatering was not noted at the time of the inspection. Two tarp basins were placed within the ROW for turbid dewatering from the foundation holes or concrete washouts. 11/2-11/10/05	- No sediment issues were noted in the wetland at this time. 11/10/05 - Release water to the ground only in well vegetated areas and if it will not reach any resource areas. 11/10/05
	-No blasting has been	-None at this time. 11/10/05

Areas of Inspection	Observation	Recommended Action
Blasting	necessary at this time except in the adjacent Archers Lane transition station. 11/10/05	
Spills and Material Storage	-A small hydraulic leak from a boom truck (approx 1 qt) was reported on 11/9/05 on the ROW on the Archers Lane side. The spill was contained and the affected soil bagged and disposed of. 11/10/05 - No further spills were noted at this inspection and the issue was handled appropriately. 11/10/05	- Continue to keep all vehicles maintained well (i.e. no apparent fluid leaks) if they will be used or stored on site - Keep adequately size fuel kits for worst case scenarios Report spills immediately, even if they are being controlled Take care not to get carried away and to be vigilant when refueling. Avoid refueling in the areas near the wetlands. Use proper storage for all materials.
Additional Observations		

Next likely scheduled	
inspection:	Thursday November 17, 2005

I have personally examined and am familiar with the information submitted in this document and all attachments and certify that based on reasonable investigation, including my inquiry of those individuals responsible for obtaining the information, the submitted information is true, accurate and complete to the best of my knowledge and belief, and I understand that any false statements made in this document or its attachments may be punishable as a criminal offense in accordance with Section 22a-6 under Section 53a-157 of the Connecticut General Statutes.

Inspector's Signature:	Diana Walden for Don Ukers	

Page 5 of 7 Transition Station Report





Overhead ROW: The photo on the left shows drilling activities for the structure that will be placed at the edge of the Archers Lane station. The photo on the right is a view of the ROW from the Archers Lane access. 11/10/05



View of the low spot/wetland crossing on the access road in from Archers Lane. Standing water in the adjacent wetlands was clear and erosion controls are in good shape. 11/10/05






Photo on the left shows a foundation with a pole structure placed for future installation. Photo on the right shows the view back towards Archers Lane and the clearing performed here to access the ROW. 11/10/05



View of a pole being off-loaded to the ROW. 11/10/05



View of the second structure in from Gallows Hill Rd. with the foundation in place and the pole ready for future installation. 11/10/05



View of a stockpile noted at a structure. Silt fence could be extended here if any sedimentation issues are noted but the work area is in uplands. 11/10/05